

Appendix H

SECTION 5B – MLS10

After 320 000 60 kN load applications



Pictorial overview of test section. HMA surface texture.



HMA surface texture. Note stripping of asphalt



Transverse crack formation

APPENDIX H



Asphalt surface texture. Plan view of test section

After 820 000 60 kN load applications



Plan views of test section with crack patterns marked with chalk



Plan views of test section with crack patterns marked with chalk

APPENDIX H



Pictorial overview of test section with crack patterns marked with chalk.